

Inspection Service + Air Filter

MC (Marking Code)

✓ Serviceable

✗ Attention Necessary

N/A (Not Applicable)

Registration Number	Make & Model	Odometer Reading	Date	Job Number
YR72LBP	Ford Custom 2.0D	46247	19/09/2024	163920

Item No.	Inside Vehicle	MC
01	Clutch	✓
02	Foot pedal rubbers	✓
03	Handbrake	✓
04	Heating & ventilation system	✓
05	Horn	✓
06	Instruments & controls	✓
07	Interior lights	✓
08	Interior locks, handles, check straps & hinges	✓
09	Interior mirror	N/A
10	Seat belts & mountings	✓
11	Seats	✓
12	Steering wheel & adjuster	✓
13	Washers & wipers	✓
14	Window mechanisms	✓
15	Windscreens	✓

Item No.	Outside Vehicle	MC
16	Bumpers	✓
17	Exterior lights	✓
18	Exterior locks & handles	✓
19	Fuel cap	✓
20	Mirrors	✓
21	Number plates	✓
22	Rear step	N/A
23	Reflectors	✓
24	Wiper blades	✓

Item No.	Engine Compartment	MC
25	Alternator belt / auxiliary belt	✓
26	Battery	✓
27	Brake fluid reservoir	✓
28	Charging system	✓
29	Cooling system	✓
30	Engine mounts	✓
31	Engine oil	✓
32	Fuel lines	✓
33	PAS fluid reservoir	N/A
34	Radiator & intercooler	✓
35	Visible wiring	✓
36	Windscreen washer bottle	✓

Item No.	Service Parts Replaced	MC
37	Engine oil & filter	✓
38	Fuel filter	N/A
39	Air filter	✓

Item No.	Underside of Vehicle	MC
40	Axle	✓
41	Axle oil	✓
42	Driveshafts / propshaft	✓
43	Exhaust system	✓
44	Gearbox & mountings	✓
45	Road springs	✓
46	Shock absorbers	✓
47	Spare wheel carrier	✓
48	Steering box / rack	✓
49	Steering joints, linkages & gaiters	✓
50	Suspension joints, linkages & gaiters	✓
51	Wheel bearings	✓

Item No.	Braking System	MC
52	Brake calipers	✓
53	Brake pads / discs (Front)	✓
54	Brake pads / discs (Rear)	✓
55	Brake pipes / hoses	✓
56	Handbrake cables / rods	✓
57	Master cylinder	✓
58	Servo unit	✓

Brake Pad Lining Remaining to Wear Sensor

N/S/F	5 mm	O/S/F	5 mm
N/S/R	5 mm	O/S/R	5 mm

Item No.	Tyres & Wheels	MC
59	Tyre condition	✓

N/S	2.8 mm	O/S	3.2 mm
5.7 mm	N/A mm	N/A mm	5.8 mm
SPARE			
	N/A mm		

60	Tyre pressures	✓
61	Wheel nuts	✓

Item No.	Final Checks	MC
62	Road test	✓
63	Service interval indicator	✓

Item No.	Details of Faults	Action Taken
	Replace pollen filter	Replaced

All vehicles inspected / serviced by Mobile Fleet Services are subject to a visual inspection only in respect of the items listed. Mobile Fleet Services cannot be held responsible for any defects not present at the time of inspection / service or any defects which cannot be detected by visual examination and road test. Mobile Fleet Services cannot accept any liability arising out of the failure of the vehicle owner or user to rectify any defects observed.